

## Important Oil Filter Notice

There is an incorrect Service Champ oil filter application in the Electronic Service Manual version ESM 15.3 for the **2004 Mitsubishi Lancer with the 4 cyl. 2.4L F.I. Engine (VIN G)**.

Refer to the following table for the correct oil filter application for this vehicle listed above.

Incorrect Oil Filter	Engine	Correct Oil Filter
OF4622	4 cyl. 2.4 (VIN G)	OF4459

The correction was made to the **Service Champ** oil filter listed above and will be included with the next ESM update that will be coming out in a couple of weeks, this will be ESM 15.4.

There is also a problem with the **VIN** code lookup for this vehicle. When the VIN is scanned for the 4 cyl. 2.4L F.I. (VIN G) engine option it will bring up the engine information including the engine oil filter as well as the lubrication information for the 4 cyl. 2.0L F.I. Turbo which is not correct for the 2.4L engine option.

This problem will be corrected and released with the ESM update that is scheduled to be available February 2016 in ESM 15.6. Until you receive ESM 15.6 we recommend you do **not** scan VIN codes on the 2004 Mitsubishi Lancers in an effort to reduce the possibility of applying an incorrect oil filter on this vehicle.

Use this information to create a TSB in order to inform your bay technicians of this change and help eliminate misapplication to this vehicle. When you create the TSB, this information is displayed in the **Technical Service Bulletins** screen that appears on the **ESM** screen during Invoicing. We encourage you to instruct your employees to use these bulletins, as they can possess critical information. For more assistance on setting up TSB's refer to your POS user's Guide on page 416.

Tim Kabachis  
ESM MGR.  
11/05/15