

## **Important Oil & Air Filter Notice**

There is an incorrect Fram oil & Air filter application in the Electronic Service Manual versions ESM 15.9 and 15.10 for the **2010 Hyundai Santa Fe 6cyl. 3.5L F.I. Engine (VIN G)**.

Refer to the following table for the correct oil & air filter application for this vehicle listed above.

<b>Incorrect Oil Filter</b>	<b>Engine</b>	<b>Correct Oil Filter</b>
<b>CH10515</b>	<b>6 cyl. 3.5 (VIN G)</b>	<b>CH10855</b>
<b>Incorrect Air Filter</b>		<b>Correct Air Filter</b>
<b>CA10661</b>		<b>CA10881</b>

The correction was made to the Fram oil & air filter listed above and will be included with the next ESM update that will be coming out at the end of July or the beginning of August in ESM 15.11.

Use this information to create a TSB in order to inform your bay technicians of this change and help eliminate misapplication to this vehicle. When you create the TSB, this information is displayed in the **Technical Service Bulletins** screen that appears on the **ESM** screen during Invoicing. We encourage you to instruct your employees to use these bulletins, as they can possess critical information. For more assistance on setting up TSB's refer to your 15.10 ISI User's Guide on page 418.

Tim Kabachis  
ESM MGR.  
06/21/17