

Important Oil Filter notice

There is an incorrect oil filter application listed for the following vendors in the Electronic Service Manual, **DuraMax**, **ECO Gard** and **Service Pro** in ESM 15.7 for the **2005 GMC Yukon Denali with the 8 cyl. 6.0L F.I. Engine (VIN U2 & U4)**.

Refer to the following table for the correct oil filter application for the vehicle listed above.

Incorrect Oil Filter	Engine	Correct Oil Filter
	8 cyl. 6.0L F.I. (VIN U2 & U4)	
DuraMax DO48		DO44
ECO Gard X2222		X4006
Service Pro M2222		M4006

The correction was made to the vendors listed above and will be included with the next ESM update that will be coming out in a few weeks, this will be ESM 15.8.

Use this information to create a TSB in order to inform your bay technicians of this change and help eliminate misapplication to this vehicle. When you create the TAB, this information is displayed in the **Technical Service Bulletins** screen that appears on the **ESM** screen during Invoicing. We encourage you to instruct your employees to use these bulletins, as they possess critical information. For more assistance on setting up TSB's refer to your POS user's guide on page 412.

Tim Kabachis
ESM MGR.
07/01/16