

LubeSoft® ISE

Automated, Web-based Estimates from LubeSoft.

To stay competitive, productivity in the shop must stay high and a credible, professional reputation must be maintained.

Using paper catalogs and calling parts stores to check application and availability takes valuable time - time which could be used to service more vehicles.

Integrated Service Estimator™ (ISE) by Epicor® now provides those tools, seamlessly integrated with your LubeSoft® system.

Vehicle: 1999 TOYOTA CAMRY 4-2164 2.2L DOHC ID: 456 Mileage: 34567 EstID: Customer PO#: Customer: J Smith

Sort By: Part Description Current Supplier: Auto Supply Inc. Add to Quote Add & Return to Quote Transfer & Exit

Job: Water Pump (CRWP)
Replace water pump and gasket, top off coolant, adjustments as required. Inspect balance of cooling system and related components.

Parts

Avl	Qty	Description	Mfr	Part#	Yrs	List	Cost	Sell	Avl Loc	Inquire
	1	ACTIVATION INFORMATION TOYOTA LONG LIFE IS RECOMMENDED NON ALCOHOL TYPE	XXX	TOYOTA LL	99-01					
	1	NEW WATER PUMP THIS PUMP IS DRIVEN OFF THE TIMING BELT. TIMING BELT SHOULD BE REPLACED W/THE PUMP.	A1	CP3099	91-01	\$92.98	\$49.99	\$92.98	In stock	[P]
	1	SEMAN WATER PUMP CARDONE INDUSTRIES	A1	SZ-1220	93-01 Core	\$72.83	\$39.99 \$4.00	\$72.83	In stock	[P]
	1	RADIATOR CAP CAPS & THERMOSTATS	MCS	7036	96-01	\$22.25	\$9.99	\$22.25	In stock	[P]

OTHER PARTS

Avl	Qty	Part Description	Mfr	Part#	List	Cost	Sell	AvlQty	Inquire
	2.00	Coolant	COOL	TOYLL	\$ 20.00	\$ 9.00	\$ 20.00		[P]

SPECIFICATION & CAPACITIES

Check	Item	Value	Unit
<input checked="" type="checkbox"/>	COOLING CAP QTS	8.0	Cooling Capacity Quarts

Labor

Select	Labor Description	Skill Level	Time	Rate (/hr)	Charges
<input checked="" type="checkbox"/>	Remove & Replace Water Pump	B	3.4 hrs.	\$ 85.00/hr	\$289.00
<input checked="" type="checkbox"/>	+ Cruise Control Interferes add	B	0.2 hrs.	\$ 85.00/hr	\$17.00
<input checked="" type="checkbox"/>	+ Eng Oil Cooler Interferes add	B	0.1 hrs.	\$ 85.00/hr	\$8.50

Job: Thermostat (CRTM)
Replace thermostat and gasket, top off coolant, adjustments as required. Inspect balance of cooling system and related components.

Parts

Avl	Qty	Description	Mfr	Part#	Yrs	List	Cost	Sell	Avl Loc	Inquire
	1	17415 / 735 THERMOSTAT AUTOPART INTERNATIONAL OE TYPE THERMOSTAT - 170 DEGREE	API	1601- 291055	96-01	\$14.07	\$9.99	\$14.07	In stock	[P]
	1	THERMOSTAT GASKET BECK/ARNEY OE TYPE - WATER OUTLET GSKT	BAR	039-0049	99	\$3.92	\$2.24	\$5.60	Qty: 0	[P]

Labor

Select	Labor Description	Skill Level	Time	Rate (/hr)	Charges
<input checked="" type="checkbox"/>	Remove & Replace Thermostat &/Or Gasket	D	0.8 hrs.	\$ 85.00/hr	\$68.00

+ Add another custom labor

Copyright © 2011 Epicor Software Corporation. Epicor is a registered trademark of Epicor Software Corporation.

Benefits & Features:

- » Quickly Launch a Pre-Populated Estimate from LubeSoft
- » All Parts, Labor and Pricing Information is Seamlessly Transferred to the Invoice
- » Epicor® Parts Network Checks Local Inventory Maintained in LubeSoft and at Local Parts Stores
- » Electronically Order Parts Directly from Local Parts Stores

Call 800.922.3099 or Visit INTS.COM

LubeSoft® ISE

Epicor® *Features:*

Interchange- An expanded cross reference parts database for PartExpert

- » Access over 22 million up-to-date listings for both Original Equipment Manufacturer (OEM) to aftermarket and aftermarket to aftermarket interchanges
- » Expand coverage to include passenger car, light truck, medium or heavy-duty truck, small engine, marine, motorcycle, agricultural, industrial, and recreational applications
- » Vehicle specifications- Fluid types, fluid capacities, torque specifications, fitting and plug sizes, spark plug gaps, ball joint tolerances, rotor discard measurement, and more.

Vehicle Identification Number (VIN) - An advanced VIN decoding technology resolves year, make, model, engine and most vehicle-specific characteristics including: body style, transmission, 2WD/4WD/AWD, hybrid vehicles, ABS, and more, eliminating the guesswork and extra time involved in traditional, application-style look-up

Call **800.922.3099** or Visit **INTS.COM**